

**1. PRODUCT NAME 300ADR CONSUMER ACTIVATOR
PRODUCT NUMBER 300ADRACT.**

11. COMPOSITION

INGREDIENTS	CONCENTRATION %	C.A.S.	IOO PPM
ACGIH TLV			
Methyl Methacrylate*	50-85	80-62-6	---
Metal Salt	0.1-1.0	Trade Secret	---
Amine Condensate	5-15	Trade Secret	---
Silicon Dioxide	1-4	Trade Secret	---
*flammable, skin and eye irritant			

M. CHEMICAL AND PHYSICAL PROPERTIES

Vapor Pressure: 29mm at 20C	Vapor Density: 3.5
Solubility in Water: Insoluble	Specific Gravity: 0.97
Boiling Point: N.A.	Appearance: light yellowish white
Odor: pungent	

IV. FLAMMABILITY AND

Flash Point: >50F (Cleveland

EXPLOSIVE PROPERTIES

Open Cup)

Recommended Extinguishing Agents: Water, foam, dry chemical or carbon dioxide
Hazardous Products Formed by Fire or Thermal Decomposition: Toxic fumes of carbon and nitrogen oxides
may evolve upon exposure to heat or open flame. Unusual Fire or Explosive Hazards: none
Compressed gases: none Solvents: none Pressure at 23C: N.A.

V. REACTIVITY DATA

Stability: stable Hazardous Polymerization: will not occur Hazardous Decomposition
Products: oxides of carbon, acid smoke
Incompatibility: oxidizers, heat, reducing agents, free radical generators

VI. SPILL OR LEAK PROCEDURES

Remove sources of ignition. Use with ventilation. Dike area to prevent spreading. Absorb on
vermiculite, sand or other inert absorbing material. Dispose of as a chemical waste in
accordance with current local, state, and federal regulations. Do not discharge into
water. Incineration recommended.

VII. STORAGE AND HANDLING PROCEDURES

Storage: Avoid storage over 1 OOF, contamination with incompatible materials.
Handling: Avoid prolonged or repeated breathing of vapor. Do not store in direct sunlight.

VIII. SHIPPING REGULATIONS

DOT and IATA Hazard Classification- ORM-D
Proper DOT Shipping Name: ORM-D

ADVANCED ADHESIVE SYSTEMS, INC. 300ADR ACT.

PAGE

2



New Warehouse Location:
Power Poxy
N53 W24794 Corporate Circle
Suite C
Sussex, WI 53089

Mailing Address:
P. O. Box 358
Sussex, Wisconsin 53089
Phone: 866-232-4681
Fax: 262-246-4828

IX. EMERGENCY TREATMENT

Eye Irritation- Immediately flush eyes with water for at least 20 minutes. Get immediate medical attention.

Skin Contact: Wash thoroughly with soap and water. Discard contaminated clothing. Do not use organic solvents on skin. If exposed to large quantities or over a long period of time, get medical attention.

Inhalation: Remove person to fresh air or artificial respiration if not breathing.

Ingestion: Give 1-2 glasses of milk or water to conscious person. Get immediate medical attention. Do not induce vomiting.

X. PERSONAL PROTECTION

Respiratory: Use proper positive air flow ventilation in work areas.

Skin: Avoid skin contact, wear impervious gloves and protective clothing if in direct contact with material. Disposable polyethylene gloves with butyl overgloves will give protection.

Eyes: Wear chemical splash goggles or side shield safety glasses.

XI. HEALTH HAZARD DATA

Hazard Categories: Immediate x delayed x flr@x_Tressure reactivity

Potential Routes of Entry: skin - x inhalation - x - ingestion-x

Symptoms of Overexposure: Possible skin and eye irritation on contact is likely.

Exposure limits:	ACGIH	OSHA	OTHER
Ingredients:			
Methyl Methacrylate	100PPM	---	---
		Target organs	
		Carcinogen	
		NTP IARC	OSHA
		None None	None

Sara Listed Ingredients: Methyl Methacrylate

XII. PREPARATION INFORMATION

ISSUE DATE: 8/11/98

PREPARED BY: Robert Batson, Technical Manager

This information is furnished without warranty, representation, or license of any kind, except that this information is accurate to the best of the Supplier's knowledge, or is obtained from sources believed by the Supplier to be accurate. No warranty is expressed or implied regarding the accuracy of this information or the results to be obtained from its use thereof. The Supplier assumes no responsibility for injuries proximately caused by use of the Material if reasonable safety procedures are not followed as stipulated in this Data Sheet. Additionally, the Supplier assumes no responsibility for injuries proximately caused by abnormal use of the Material even if reasonable safety procedures are followed. Buyer assumes the risk in its use of the Material.



New Warehouse Location:
Power Poxy
N53 W24784 Corporate Circle
Suite C
Sussex, WI 53089

Mailing Address:
P. O. Box 358
Sussex, Wisconsin 53089
Phone: 866-232-4681
Fax: 262-245-4828